



## Vehicle History Report™

### 2014 FORD FOCUS SE

VIN: 1FADP3K25EL129392  
HATCHBACK 4 DR  
2.0L I4 F DOHC 16V  
GASOLINE  
FRONT WHEEL DRIVE  
Original Window Sticker



No accidents or damage reported to CARFAX



22 Service history records



At least 1 open recall



2 Previous owners



Types of owners: Personal lease, Personal



136,959 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/9/26 at 10:30:53 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



### Additional History

Not all accidents / issues are reported to CARFAX

#### Owner 1

#### Owner 2

#### Total Loss

No total loss reported to CARFAX.



No Issues Reported



No Issues Reported

#### Structural Damage

No structural damage reported to CARFAX.



No Issues Reported



No Issues Reported

#### Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues Reported



No Issues Reported

#### Odometer Check

No indication of an odometer rollback.



No Issues Indicated



No Issues Indicated

#### Accident / Damage

No accidents or damage reported to CARFAX.



No Issues Reported



No Issues Reported

#### Manufacturer Recall

At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.



No Recalls Reported

Recall Reported

#### Basic Warranty

Original warranty estimated to have expired.

Warranty Expired

Warranty Expired

<div> <div>CARFAX</div> <div>Title History</div> </div> <div>CARFAX guarantees the information in this section</div>	Owner 1	Owner 2
<div>Damage Brands</div> <div>Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon</div>	<div> <div>✓</div> <div>Guaranteed No Problem</div> </div>	<div> <div>✓</div> <div>Guaranteed No Problem</div> </div>
<div>Odometer Brands</div> <div>Not Actual Mileage   Exceeds Mechanical Limits</div>	<div> <div>✓</div> <div>Guaranteed No Problem</div> </div>	<div> <div>✓</div> <div>Guaranteed No Problem</div> </div>
<div> <div> <div>BUYBACK</div> <div>CARFAX</div> <div>GUARANTEE</div> </div> <div> <div>GUARANTEED</div> <div>- None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.</div> <div>View Terms   View Certificate</div> </div> </div>		

<div> <div>CARFAX</div> <div>Ownership History</div> </div> <div>The number of owners is estimated</div>	Owner 1	Owner 2
Year purchased	2014	2017
Type of owner	Personal lease	Personal
Estimated length of ownership	3 yrs. 1 mo.	8 yrs. 7 mo.
Owned in the following states/provinces	Michigan, Illinois	Illinois
Estimated miles driven per year	1,544/yr	28,518/yr
Last reported odometer reading	4,896	136,959




<div> <div>CARFAX</div> <div>Detailed History</div> </div>			
<div> <div> <div> <div>Owner 1</div> <div>Purchased: 2014</div> </div> <div> <div> <div>Low mileage!</div> <div>This owner drove less than the industry average of 15,000 miles per year.</div> </div> </div> <div> <div>Personal Lease Vehicle</div> <div>1,544 mi/yr</div> </div> </div> </div>			
Date	Mileage	Source	Comments
08/15/2013		Ford Motor Company	<div>Vehicle manufactured and shipped to original dealer</div> <div>Original Window Sticker</div> <div> <div> <div> <div>26</div> <div>MPG</div> </div> <div> <div>\$1,350</div> <div>MSRP</div> </div> <div> <div>\$2,050</div> <div>MSRP</div> </div> </div> </div>
08/15/2013		Jack Demmer Ford Wayne, MI	Vehicle offered for sale




734-721-2600

★ 4.7 / 5.0

529 Verified Reviews

♥ 7,256 Customer Favorites

09/03/2013 24	Gorno Ford Woodhaven, MI 734-676-0031  ★ 4.6 / 5.0 741 Verified Reviews ♥ 6,224 Customer Favorites	<b>Vehicle offered for sale</b>
09/30/2013	Gorno Ford Woodhaven, MI 734-676-0031  ★ 4.6 / 5.0 741 Verified Reviews ♥ 6,224 Customer Favorites	 <b>Vehicle serviced</b> - Pre-delivery inspection completed
10/17/2013	Gorno Ford Woodhaven, MI 734-676-0031  ★ 4.6 / 5.0 741 Verified Reviews ♥ 6,224 Customer Favorites	 <b>Vehicle serviced</b> - Pre-delivery inspection completed - Wheel locks installed
02/27/2014 48	Gorno Ford Woodhaven, MI 734-676-0031  ★ 4.6 / 5.0 741 Verified Reviews ♥ 6,224 Customer Favorites	<b>Vehicle sold</b>
02/27/2014	Gorno Ford Woodhaven, MI 734-676-0031  ★ 4.6 / 5.0 741 Verified Reviews ♥ 6,224 Customer Favorites	 <b>Vehicle serviced</b> - Wiper(s) replaced
03/06/2014 98	Michigan Motor Vehicle Dept. Taylor, MI	<b>Title or registration issued</b> - First owner reported - Titled or registered as personal lease vehicle
01/22/2015	Michigan Motor Vehicle Dept. Taylor, MI	<b>Registration issued or renewed</b>

01/20/2016		Michigan Motor Vehicle Dept. Taylor, MI		Registration issued or renewed
01/23/2017		Michigan Motor Vehicle Dept. Taylor, MI		Registration issued or renewed
02/24/2017	4,795	Gorno Ford Woodhaven, MI 734-676-0031 ★ 4.6 / 5.0 741 Verified Reviews ❤️ 6,224 Customer Favorites		Vehicle serviced - Door latch repaired/replaced
04/14/2017	4,802	K&S FORD Fairbury, IL 815-692-2016 ★ 4.8 / 5.0 44 Verified Reviews ❤️ 10 Customer Favorites		Vehicle offered for sale
04/17/2017		Auto Auction 		Vehicle sold <div>Millions of used vehicles are bought and sold at auction every year.</div>
04/19/2017	4,852	K&S FORD Fairbury, IL 815-692-2016 ★ 4.8 / 5.0 44 Verified Reviews ❤️ 10 Customer Favorites		Vehicle serviced - Maintenance inspection completed
04/27/2017	4,896	K&S FORD Fairbury, IL 815-692-2016 ★ 4.8 / 5.0 44 Verified Reviews ❤️ 10 Customer Favorites		Vehicle sold
04/27/2017		Illinois Motor Vehicle Dept.		Vehicle purchase reported
05/03/2017		Illinois Motor Vehicle Dept. Morris, IL		Registration issued or renewed









Owner 2

Personal Vehicle

Purchased: 2017

28,518 mi/yr

Date	Mileage	Source		Comments
05/11/2017		Illinois Motor Vehicle Dept. Morris, IL		<b>Title issued or updated</b> - New owner reported - Loan or lien reported - Vehicle color noted as Silver
10/10/2017	15,229	McCoy TIRE & AUTO Channahon, IL 815-467-2258  ★ 4.7 / 5.0 6 Verified Reviews ♥ 13 Customer Favorites		<b>Vehicle serviced</b> - Oil and filter changed
01/02/2018	20,090	Ewert's Automotive Channahon, IL 815-467-1117  ★ 4.9 / 5.0 166 Verified Reviews ♥ 125 Customer Favorites		<b>Vehicle serviced</b>
02/07/2018		Illinois Motor Vehicle Dept. Morris, IL		<b>Registration issued or renewed</b>
03/14/2018	25,629	Ewert's Automotive Channahon, IL 815-467-1117  ★ 4.9 / 5.0 166 Verified Reviews ♥ 125 Customer Favorites		<b>Vehicle serviced</b> - Fluids checked - Tires rotated
04/18/2018	30,960	Ewert's Automotive Channahon, IL 815-467-1117  ★ 4.9 / 5.0 166 Verified Reviews ♥ 125 Customer Favorites		<b>Vehicle serviced</b> - Fluids checked
07/11/2018	35,648	Ewert's Automotive Channahon, IL 815-467-1117  ★ 4.9 / 5.0 166 Verified Reviews ♥ 125 Customer Favorites		<b>Vehicle serviced</b> - Fluids checked
08/23/2018	41,502	Ewert's Automotive Channahon, IL 815-467-1117		<b>Vehicle serviced</b> - Fluids checked - Tires rotated

★ 4.9 / 5.0  
166 Verified Reviews  
♥ 125 Customer Favorites

10/15/2018 47,046

Ewert's Automotive  
Channahon, IL  
815-467-1117



**Vehicle serviced**

- Fluids checked

★ 4.9 / 5.0  
166 Verified Reviews  
♥ 125 Customer Favorites

10/24/2018

Ford Motor Company

**Manufacturer Safety recall issued**

- NHTSA #18V735  
- Recall #18S32 FUEL TANK  
DEFORMATION  
- Status: Remedy Available

Locate an authorized Ford or Lincoln  
dealer or call 866-436-7332 to obtain  
more information

➔ **Learn more about this recall**

**Description:** ON YOUR VEHICLE, THE PCM SOFTWARE MAY NOT ADEQUATELY DETECT A STUCK-OPEN CANISTER PURGE VALVE (CPV) WITHIN THE FUEL VAPOR SYSTEM. IF THE CPV MALFUNCTIONS AND STICKS OPEN, IT CAN LEAD TO EXCESSIVE VACUUM IN THE FUEL VAPOR SYSTEM, POTENTIALLY DEFORMING THE PLASTIC FUEL TANK. THIS CAN CAUSE THE FOLLOWING SYMPTOMS: ILLUMINATED MALFUNCTION INDICATOR LAMP (MIL) WITH CERTAIN DIAGNOSTIC TROUBLE CODES (DTCS) INACCURATE OR ERRATIC FUEL GAUGE INDICATION INACCURATE DISTANCE TO EMPTY (DTE) ENGINE STALL AND/OR OTHER DRIVABILITY CONCERNS RELATED TO STUCK OPEN CPV

THIS MAY RESULT IN AN ENGINE STALL WHILE DRIVING WITHOUT WARNING OR WITHOUT THE ABILITY TO RESTART, AND CAN INCREASE THE RISK OF A CRASH.

**Remedy:** PARTS AND SOFTWARE ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO UPDATE YOUR VEHICLE S PCM SOFTWARE, CHECK FOR DTCS OR OTHER EVIDENCE OF A LEAKING CPV, AND PERFORM ANY ADDITIONAL REQUIRED REPAIRS AS REQUIRED, FREE OF CHARGE (PARTS AND LABOR).IF YOU INSTALLED A FORD PERFORMANCE CALIBRATION ON YOUR 2013-2018 FOCUS ST, YOU MUST STILL HAVE THIS SAFETY RECALL PERFORMED. YOU MAY CONTACT FORD PERFORMANCE TO OBTAIN AN UPDATED FORD PERFORMANCE CALIBRATION FOR YOUR VEHICLE AFTER THIS RECALL HAS BEEN COMPLETED.CONTACT THE FORD PERFORMANCE TECHLINE BY CALLING 800-367-3788 OR ONLINE [HTTPS://PERFORMANCEPARTS.FORD.COM/CONTACT-US](https://performanceparts.ford.com/contact-us)

01/10/2019 53,921

Ewert's Automotive  
Channahon, IL  
815-467-1117



**Vehicle serviced**

- Fluids checked  
- Oil and filter changed  
- Tires rotated

★ 4.9 / 5.0  
166 Verified Reviews  
♥ 125 Customer Favorites

02/22/2019

Illinois

**Registration issued or renewed**

Motor Vehicle Dept.  
Morris, IL

02/26/2019 58,130

McCoy TIRE & AUTO  
Channahon, IL  
815-467-2258

★ 4.7 / 5.0

6 Verified Reviews

♥ 13 Customer Favorites



**Vehicle serviced**

- Tire repaired

03/18/2019 59,747

Ewert's Automotive  
Channahon, IL  
815-467-1117

★ 4.9 / 5.0

166 Verified Reviews

♥ 125 Customer Favorites



**Vehicle serviced**

- Fluids checked  
- Oil and filter changed  
- Tires rotated

04/08/2019 61,366

Ewert's Automotive  
Channahon, IL  
815-467-1117

★ 4.9 / 5.0

166 Verified Reviews

♥ 125 Customer Favorites



**Vehicle serviced**

- Tire(s) replaced

06/13/2019 67,101

McCoy TIRE & AUTO  
Channahon, IL  
815-467-2258

★ 4.7 / 5.0

6 Verified Reviews

♥ 13 Customer Favorites



**Vehicle serviced**

- Oil and filter changed

12/17/2019 80,339

McCoy TIRE & AUTO  
Channahon, IL  
815-467-2258

★ 4.7 / 5.0

6 Verified Reviews

♥ 13 Customer Favorites



**Vehicle serviced**

- Oil and filter changed  
- Tire condition and pressure checked  
- Tire pressure monitoring system serviced  
- Tire(s) balanced  
- Tire(s) mounted  
- Tire(s) replaced

03/18/2020

Illinois  
Motor Vehicle Dept.  
Morris, IL

**Registration issued or renewed**

- Correction to record

06/09/2020

Ford Motor Company

**Manufacturer Safety recall issued**

- NHTSA #20V331  
- Recall #20S30 DOOR LATCH REPEAT REPAIR  
- Status: Remedy Available




Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

Learn more about this recall


**Description:** YOUR VEHICLE WAS PREVIOUSLY REPAIRED UNDER SAFETY RECALL 15S16 OR 16S30. DURING THAT REPAIR, YOUR VEHICLES DOOR LATCHES WERE TO BE REPLACED TO HELP REDUCE THE RISK OF DOORS NOT CLOSING OR DOORS OPENING WHILE DRIVING. IT IS POSSIBLE THAT ONE OR MORE OF YOUR DOOR LATCHES WAS NOT REPLACED OR MAY NOT HAVE BEEN REPLACED CORRECTLY.

IF A DOOR LATCH WAS NOT REPLACED, THERE IS STILL A RISK THAT THE PAWL SPRING TAB INSIDE THE DOOR LATCH COULD BREAK. THIS CONDITION WILL TYPICALLY PREVENT THE DOOR FROM LATCHING. IN CERTAIN SITUATIONS, WHERE THE DOOR IS ABLE TO BE CLOSED, THE DOOR MAY UNLATCH WHILE DRIVING, INCREASING THE RISK OF INJURY

**Remedy:** THE DOOR LATCH DATE CODES IN YOUR VEHICLE NEED TO BE INSPECTED TO VERIFY THAT THE PREVIOUS DOOR LATCH RECALL REPAIR WAS COMPLETED AS INTENDED. FOR YOUR CONVENIENCE AND TO ENCOURAGE THE CONTINUED SOCIAL DISTANCING REQUIREMENTS BY MANY STATE AND LOCAL GOVERNMENTS RELATED TO COVID-19, FORD IS PROVIDING YOU WITH THE OPTION TO COMPLETE THIS SIMPLE INSPECTION YOURSELF USING THE ATTACHED SELF-INSPECTION SHEET. BY UTILIZING THIS OPTION, YOU SHOULD NOT NEED TO TAKE YOUR VEHICLE TO YOUR DEALER UNLESS YOUR VEHICLE IS EXHIBITING DOOR LATCHING CONCERNS DOOR WILL NOT LATCH OR OPENS WHILE DRIVING. IN THE UNLIKELY EVENT THAT THE SYSTEM CANNOT CONFIRM THE LATCHES ON YOUR VEHICLE BASED ON YOUR INPUT, OR IF YOUR VEHICLE IS EXHIBITING DOOR LATCHING CONCERNS, YOU WILL NEED TO TAKE YOUR VEHICLE TO YOUR DEALERSHIP FOR ADDITIONAL INSPECTION AND/OR REPAIRS. IF YOU DO NOT WISH TO COMPLETE THIS INSPECTION YOURSELF, YOUR DEALER WILL INSPECT YOUR VEHICLE FOR YOU

07/01/2020	93,221	McCoy TIRE & AUTO Channahon, IL 815-467-2258 ★ 4.7 / 5.0 6 Verified Reviews ♥ 13 Customer Favorites	 <b>Vehicle serviced</b> - Brake fluid flushed/changed - Oil and filter changed
03/08/2021		Illinois Motor Vehicle Dept. Morris, IL	<b>Registration issued or renewed</b>
03/19/2021	113,584	McCoy TIRE & AUTO Channahon, IL 815-467-2258 ★ 4.7 / 5.0 6 Verified Reviews ♥ 13 Customer Favorites	 <b>Vehicle serviced</b> - Tire repaired
11/18/2021	132,769	McCoy TIRE & AUTO Channahon, IL 815-467-2258 ★ 4.7 / 5.0 6 Verified Reviews ♥ 13 Customer Favorites	 <b>Vehicle serviced</b> - Tire repaired



01/15/2022	136,959	McCoy TIRE & AUTO Channahon, IL 815-467-2258 ★ 4.7 / 5.0 6 Verified Reviews ❤️ 13 Customer Favorites	 <b>Vehicle serviced</b> - Oil and filter changed
01/24/2022	Illinois Motor Vehicle Dept. Morris, IL	<b>Registration issued or renewed</b>	
10/20/2022	Illinois Motor Vehicle Dept. Morris, IL	<b>Registration issued or renewed</b>	
12/08/2022	Ford Motor Company	<b>Manufacturer Customer Satisfaction issued</b> - Program #19N08 TRANSMISSION CLUTCH SHUDDER -TRANSMISSION CLUTCH WARRANTY EXTENSION  Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information	
02/08/2023	Illinois Motor Vehicle Dept. Morris, IL	<b>Registration issued or renewed</b>	
02/19/2024	Illinois Motor Vehicle Dept. Morris, IL	<b>Registration issued or renewed</b>	
12/04/2024	Ford Motor Company	<b>Manufacturer Customer Satisfaction issued</b> - Program #24N07 ONE-TIME CANISTER PURGE VALVE REPLACEMENT  Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information	
01/22/2025	Illinois Motor Vehicle Dept. Channahon, IL	<b>Registration issued or renewed</b>	

Have Questions? Please visit our Help Center at [www.carfax.com](http://www.carfax.com).



## Glossary

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### **Ford or Lincoln Mercury Recall**

The Ford Motor Company provides CARFAX with Field Service Action and recall information regarding safety, compliance and emissions programs announced since 2000 for a specific vehicle. For complete information regarding programs or concerns about this vehicle, please contact a local Ford or Lincoln Mercury Dealer.

### **Manufacturer Recall**

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

### **New Owner Reported**

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

### **Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### **Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

**Follow Us:**



[facebook.com/CARFAX](https://facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



[About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.  
1/9/26 10:30:53 AM (CST)

